

**OPTION****A****A-Wing  
Classroom  
Upgrades/Hall  
Paint – Approx  
16 Classrooms**

New paint, tack board on classroom walls up to 8'.

Refinish floors or replace with carpet.

Repair/ Replace ceiling.

Upgrade/ renovate cabinetry and shelving.


**\$2,001,600****OPTION****B****Rubberized Track,  
Natural Turf Field**

Full rubberized track per original plans with inside and outside curbs, natural sod sport field inside of track curb, new irrigation on field connected to existing irrigation system of the school site, non-irrigated hydroseed erosion control mix outside of track area.

This option would require the removal/relocation of Migrant Head Start portables (2) or the removal/relocation of the existing baseball field.

**\$2,011,400****OPTION****C****Synthetic Turf  
Field with  
rectangular  
curb, no track**

Synthetic Turf Field with rectangular curb outlining entire perimeter of synthetic turf field.

**\$1,922,574**

**YOUR OPINION IS VALUED. IF YOU CANNOT ATTEND, PLEASE LET US  
KNOW YOUR PREFERENCE BY COMPLETING THE SURVEY AT**

**<https://forms.gle/CdJcULHT16TXV8wa9>**